



**Technical Service
Information Bulletin**

September 12, 2003

Title:

TRIM GARNISH LOOSE

Models:

All Models

BO007-03

BODY

Introduction Customers may experience an interior trim panel either loose or fitting poorly due to a deformed or missing clip. When a trim garnish (A, B, C or D pillar garnishes, door trim panel, etc.) is removed and reinstalled using the old clips, it may cause the garnish to exhibit a loose condition. To prevent this condition from occurring, ensure that new clips are utilized for all attachment points every time a garnish is reinstalled. When installing new parts, use either the new clips supplied with the part, or order new clips. Refer to the parts catalog for specific part numbers.

Applicable Vehicles

- All models.

**Warranty
Information**

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
N/A	Not Applicable to Warranty	—	—	—	—

