



TOYOTA TECHNICAL SERVICE BULLETIN

REF.: ENGINE
NO.: EG001-96
DATE: JANUARY 26, 1996
MODEL: L-C & TER

ECM STANDARDIZATION

Page 1 of 1

To standardize parts availability, 1996 model Land Cruiser and Tercel ECMs may also be used on respective 1995 model Land Cruisers and Tercels.

DIFFERENCES BETWEEN PREVIOUS AND NEW SUPPLY ECMs:

1995 MODEL ECM	1996 MODEL ECM
For Fuel Trim Malfunction, MIL turns "ON" with Diagnostic Trouble Code (DTC) PO170 whenever the air fuel ratio is excessively lean or rich.	For Fuel Trim Malfunction, MIL turns "ON" with DTC PO171 for excessively <u>lean</u> air fuel ratio. DTC PO172 applies to excessively <u>rich</u> air fuel ratio.

NOTE: Use 1996 Land Cruiser Repair Manual (RM451U) or Tercel Repair Manual (RM440U) as appropriate, to diagnose 1995 model Land Cruisers or Tercels which have a new ECM installed.