



Technical Service
BULLETIN

November 21, 1997

Title:

PUBLICATION CORRECTION INFORMATION

Models:

'95-'97 T100 & TACOMA, '96-'97 RAV4 & 4RUNNER, '97 CELICA & LAND CRUISER

PG011-97
PRODUCT GENERAL INFORMATION

Introduction Corrections have been made in the repair manuals listed below. A brief description of each correction is provided. For further details, refer to the appropriate Correction Page (attached to this TSB for Dealer/Region/PD distribution). Please insert these correction pages in their corresponding publication.

NOTE:

When ordering a technical publication (i.e. Repair Manual, Electrical Wiring Diagram) from the MDC, any Correction Page(s) associated with that particular Publication, will be automatically included with your order.

Additional Correction Pages are available through the Dealer Support Material Network (MDC NPM System) via the corresponding part numbers from the following tables:

Parts Information

PUBLICATION	NUMBER	PAGE(S)	DESCRIPTION	PART NUMBER
'95 T100 Repair Manual	RM414U1	EG-55	5VZ-FE ENGINE – ENGINE MECHANICAL. CYLINDER HEADS INSTALLATION-Step 1, B <i>Hint</i> : revised.	00400-RM414-7010
'95 Tacoma Repair Manual	RM433U1	EG-55	5VZ-FE ENGINE – ENGINE MECHANICAL. CYLINDER HEADS INSTALLATION-Step 1, B <i>Hint</i> : revised.	00400-RM433-7011
'96 RAV4 Repair Manual	RM447U	IN-36	INTRODUCTION – VEHICLE LIFT AND SUPPORT LOCATIONS. VEHICLE LIFT AND SUPPORT LOCATIONS - All illustrations revised. SUPPORT POSITIONS for Safety Stand And Swing Arm Type Lift shown separately.	00400-RM447-6051
'96 4Runner Repair Manual	RM480U	BR-29	BRAKE – ABS ACTUATOR. INSPECTION – Illustration for Steps 2 and 3 revised. Step 2, (a) revised.	00400-RM480-7011
		EM-47	5VZ-FE ENGINE – ENGINE MECHANICAL. CYLINDER HEAD–Step 2 <i>Hint</i> : revised	
'96 T100 Repair Manual	RM449U	EG-51	5VZ-FE ENGINE – ENGINE MECHANICAL. CYLINDER HEADS INSTALLATION – Step 1 B <i>Hint</i> : revised	00400-RM450-7011
'96 Tacoma Repair Manual	RM450U	EG-50	5VZ-FE ENGINE – ENGINE MECHANICAL. CYLINDER HEADS INSTALLATION – Step 1 B <i>Hint</i> : revised	00400-RM450-7011



Parts
Information

PUBLICATION	NUMBER	PAGE(S)	DESCRIPTION	PART NUMBER
'97 Celica Repair Manual	RM501U	BE–46	BODY ELECTRICAL – POWER WINDOW CONTROL SYSTEM. POWER WINDOW CONTROL SYSTEM – PARTS LOCATION illustration revised.	00400-RM501-7010
'97 RAV4 Repair Manual	RM505U	IN–36	INTRODUCTION – VEHICLE LIFT AND SUPPORT LOCATIONS. VEHICLE LIFT AND SUPPORT LOCATIONS – Illustrations revised to show new SUPPORT POSITIONS for Swing Arm Type Lift.	00400-RM505-6051
'97 4Runner Repair Manual	RM509U	BR–29	BRAKE – ABS ACTUATOR. INSPECTION – Illustration for Steps 2 and 3 revised. Step 2, (a) revised.	00400-RM509-7011
		EM–47	5VZ-FE ENGINE – ENGINE MECHANICAL. CYLINDER HEAD – Step 2, <i>Hint</i> : revised.	
'97 Land Cruiser Repair Manual	RM510U	BR–15	BRAKE – FRONT BRAKE. FRONT BRAKE COMPONENTS INSPECTION AND REPAIR – Step 3. MEASURE DISC RUNOUT – Text revised to include <i>grind it on a “on-car” brake lathe.</i>	00400-RM510-6042
		BR–19	BRAKE – REAR BRAKE (Disc Brake). REAR DISC BRAKE COMPONENTS INSPECTION AND REPAIR – Step 3. MEASURE DISC RUNOUT – Text added for procedures if runout is at greater than maximum.	
'97 T100 Repair Manual	RM507U	BR–50	BRAKE– ANTI-LOCK BRAKE SYSTEM (ABS) ABS ACTUATOR INSPECTION – Step 2 revised.	00400-RM507-7011
		BR–52	BRAKE– ANTI-LOCK BRAKE SYSTEM (ABS) ABS ACTUATOR INSPECTION – Step 8 revised.	
'97 Tacoma Repair Manual	RM508U	EG–50	5VZ-FE ENGINE – ENGINE MECHANICAL. CYLINDER HEADS INSTALLATION – Step 1, B <i>Hint</i> : revised.	00400-RM508-7011