

REF.: SPECIAL SERVICE
TOOLS
NO.: SS95-002
DATE: JULY 21, 1995
MODEL: ALL MODELS

1995 TOYOTA SPECIAL SERVICE TOOLS

Page 1 of 4

The following TSB contains information regarding the 1995 Special Service Tools (SST's). Both the Essential and Available SST's are listed by tool number, tool name, model application, illustration/usage (for selected SST's) and appropriate section reference in repair manual. All Special Service Tools (SST's) may be ordered by contacting OTC at 1-800-933-8335.

SPECIAL SERVICE TOOL INDEX:

The following SST's have become essential since TSB # SS94-001 dated 04/15/94:

ESSENTIAL SST'S		
Tool Number	Tool Name	Page Number
01001895-005	Diagnostic Toolset Program Card Kit	2
00002-04210-01	Wire Harness Repair Kit B	2



The following SST's have become available since TSB # SS94-001 dated 04/15/94:


AVAILABLE SST'S		
Tool Number	Tool Name	Page Number
—	All Other Available SST's	3 & 4



RECOMMENDED SST (V-BOB ACCESSORY)		
Tool Number	Tool Name	Page Number
02001967	ECU Connector Exchange Wire Harness # 7	4

ESSENTIAL SST'S:

Please refer to the following tables to locate applicable models and repair manual procedures.



DIAGNOSTIC TOOLSET PROGRAM CARD KIT		P/N – 01001895–005
USAGE	APPLICATION	R/M SECTION
 <div data-bbox="557 428 784 600">Most current software and manual update pages</div> 	All Models	N/A
Computer System Diagnosis		

WIRE HARNESS REPAIR KIT B		P/N – 00002–04210–01
USAGE	APPLICATION	R/M SECTION
	All Models	N/A
Wire Harness Repair		




AVAILABLE SST'S:

TOOL NUMBER	TOOL NAME	TOOL NAME	R/M SECTION
01001872	Asian Imports Cartridge (For Diagnostic Tester)	Other Asian Imports	N/A
01001929	GM/Ford/Chrysler Cartridge (For Diagnostic Tester)	GM/Ford/Chrysler	N/A
00002-62195	4-Way Circuit Tester Kit	All With Port Installed Trailer Hitch	N/A
07112-76040	Magnetic Clutch Stopper	1995 Previa	AC
09248-55050	Valve Clearance Adjust Tool Set	1995 Land Cruiser	EG
09527-10011	Rear Axle Shaft Bearing Remover	1995 Land Cruiser	SR
09612-07010	Main Shaft Retaining Ring Replacer/Remover	1995 Avalon	SR
09631-00350	Steering Rack Cover	1995 Tacoma	SR
09727-30030	Coil Spring Compressor	1995 Tacoma	SA
09922-10010	Variable Open Wrench	All Models	SR
09950-60010	Universal Replacer Set	1995 Land Cruiser 1995 Tacoma	EG, SR, SA
09950-70010	Universal Handle Set	1995 Land Cruiser	EG, SR, SA
09999-4938A	Magnetic Mount Antenna	Cell Phone	N/A
09999-84406	25-Pin Test Connector	Cell Phone	N/A
02001968	ECU Connector Exchange Wire Harness #8 (For Vehicle Break-Out Box) TDS Diagnosis	Currently No Toyota Application 1995 LS 400	BE



RECOMMENDED SST (V-BOB ACCESSORY):

ECU CONNECTOR EXCHANGE WIRE HARNESS #7		P/N – 02001967
USAGE	APPLICATION	SECTION
<div></div> <div>Antilock Brake System Diagnosis</div>	<div>94–95 Celica</div> <div>94–95 4–Runner</div> <div>94–95 T100</div> <div>1995 Tacoma</div>	<div>BR</div>

